



BIARD LLC, Moscow

COMMENT

on using Isollat liquid ceramic insulation material

Problem to be fixed:

Wet corner of convergence of external walls of the room, as a result of condensation. In our opinion, the problem occurred due to violations in the design phase.

Solution

Isollat liquid ceramic insulation coating was used. After removing the layer of putty in the problem area, the room corner was dried out with a heat gun, primed and coated with Isollat: 4 layers 0.5 mm each, then plastered and painted.

Result:

Condensation has been eliminated, the wall feels dry and warm.